Annexure D

BUILDING SAFETY CERTIFICATE

No.	878				Dated:	21.04.2	2.5
It is certified that the existing building Kamal Kumari Devi Model Sehoel name of the							
building or premises) at Raghunathgany, Haridas nagar, Murshidabad							
Detail	of Block(s) in	Block	Block	Block	Block	Block	Block
school		(1)	(2)	(3)	(4)	(5)	(6)
No. of	Floor(s) in the	9+3	-		_	_	_
Block		3rd Floor					
The building is owned/occupied by Kamal Kumari Devi Model School (name							
of the Institution) have complied with the Building safety requirements in accordance with National							
Building code Rules, and verified by the officers concerned of Jangibur Municipality ame of							
Department/ Govt.) on 21.04.25 (date of inspection) in the presence of							
Mita Ghosh (name and addresses of the							
Manager/Secretary or his representative) and that the building/premises is fit for occupancy for							
running school with effect from 2025, Aprifor a period of years in accordance							
with rule and subject to compliance of the specific conditions as appended.							
1. Soil Condition							
2. Structure of building. 3. Building Condition. 4. Sufficient space for accomodation.							
3. Building Condition.							
4. Sufficient space for accomodation.							
Issued on 21.4.25 at 4.00 P.M. by							
* Strike out whichever is not applicable. In case of block is more than six use separate sheet for							
detail. Sub-Asst. Engineer 21/4/							
Signature with Seal:							
Name: Sandif Kumar Singha							
कनल कुनारी हैनी महेल रक्त							
KAMAL KUMARI DEVI MODEL SCHOOL Name & Address of Department/ Office: Jangibus							
(CBSE Aff. No 2430194) Chairman Municipality 65 Haridesnegar, Rayhunathgani K. K. D. M. School P.S. + P.ORaghunathgany							
, (इरिवायनगर रयुनायांथ, MSD	9	Haridasnagar, R	agh unathgani		t- Mursh	
			Murshidaba	ad (W.B.)		- 742225	